

Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

March 29, 2011

Certified Return Receipt Requested 7009 3410 0001 4203 1546

Tracy Burnham Eureka Rock Products, LLC 1584 South 580 East American Fork, Utah 84003

Subject: Division Directive, Eureka Rock Products, Eureka Rock, S/023/0094, Juab County,, Utah

Dear Mr. Burnham:

There are deficiencies in your reclamation surety for the above referenced mine that need to be rectified. In a letter dated September 28, 2010, the Division informed you that the reclamation surety needed to be increased. As of today, the Division has not received the additional surety. In addition, the Division noticed that there were rock overhangs on the site. The overhangs must be removed.

Within 30 days of receipt of this letter, you are hereby directed to:

- Revise your reclamation surety by increasing the amount to an appropriate level mine from \$15,300.00 to \$20,300.00 (three-year escalation to 2012) or \$20,800 (five-year escalation to 2014).
- Remove the rock overhangs at the site.

Failure to update the reclamation surety as directed may result in enforcement action being taken by the Division which may include withdrawal of your permit and an order to commence reclamation of the site immediately.

If you have questions or concerns regarding this letter, please contact me at (801) 538-5261 or Wayne Western at 538-5263. Thank you for your help in completing this very important regulatory requirement.

Sincerely.

Paul B. Baker

Minerals Program Manager

PBB:whw::pb

Cc: <u>Jerry Mansfield@BLM.gov</u>

Penny Berry, DOGM

